

# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5

## 77 WEST JACKSON BOULEVARD CHICAGO, ILLINOIS 60604

DATE:

DEC 0 5 2019

**SUBJECT:** 

CLEAN AIR ACT INSPECTION REPORT

Dynamic Diesel Performance & Machine, Inc., New Baltimore, Michigan

FROM:

Cody Yarbrough, Environmental Engineer

AECAB (MN/OH)

THRU:

Brian Dickens, Section Chief

AECAB (MN/OH)

TO:

File

### **BASIC INFORMATION**

Facility Name: Dynamic Diesel Performance & Machine, Inc.

Facility Location: 49716 Leona Dr. New Baltimore, Michigan 48051

Date of Inspection: October 30, 2019

## **EPA Inspector(s):**

1. Cody Yarbrough, Environmental Engineer

#### Other Attendees

1. Paul Cuppetelli, Owner, Dynamic Diesel Performance

Contact Email Address: DynamicDiesel60@hotmail.com

Purpose of Inspection: Emission control device tampering on vehicles and engines.

Facility Type: Engine rebuilding

Regulations Central to Inspection: Emission control device tampering prohibitions. CAA

Section 203(a)(3)(a)-(b).

**Arrival Time:** 11:55 AM, CDT **Departure Time:** 12:09 PM, CDT

Inspection Type:	
$\boxtimes$	Unannounced Inspection
	Announced Inspection
<u>Open</u>	NING CONFERENCE
$\boxtimes$	Credentials Presented
$\boxtimes$	CBI warning to facility provided
The fo	ollowing information was obtained verbally from Mr. Cuppetelli unless otherwise noted.
Dyna	ess Description: mic Diesel Performance rebuilds engines and manufactures certain engine parts. The any does not conduct exhaust work or performance tuning.
<u>Tour</u>	RINFORMATION
EPA	toured the facility: Yes
Data Collected and Observations: The shop contained several engines but no vehicles.	
Photo	os and/or Videos: were not taken during the inspection.
Field Measurements: were not taken during this inspection.	
SIGN.	ATURES
	on Chief: Bulus Stocus Date: 12/5/19
Section	on Chief: Sular Stocus Date: 12/5/19